ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0007, W0009, W0005, W0012, W0010, W0014	NA	NISARGA LAYOUT
Segment No.	**Total Length (m)**	
12/C-W0007/S071917	121.12	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	121.12	77.524734	13.081618	77.524753	13.080524	W0018	W0006

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
PROVIDING BS SLAB DRAIN AND METALING IN KERRE KODI NEAR NISARGA LAYOUT AT ABBIGERE	1800000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	DRAN AND METALLING
Tender	**Work Details**	**Job No. / Work Code**
Tender	DRAN AND METALLING WORK	012-14-000013
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/219/13-14	27/01/2014	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B T RAVI KUMAR		1698334.00
Phone No.	**E-Mail ID**	
7353903103		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		ravi n k
Date of Inspection	**Remarks**	
12/03/2016		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	NAGARAJ	12/03/2016	11/04/2016	COMPLETED
EE	JOGI SIDHE GOWDA	12/03/2016	11/04/2016	COMPLETED
AEE	RAMACHADRA MURTHY	12/03/2016	11/04/2016	COMPLETED
AE	RAVI	12/03/2016	11/04/2016	COMPLETED
AE	RAVI	12/03/2016	11/04/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0007, W0009, W0005, W0012,